Certificate of Location of Government Corner

ID#: 710406 **Description:** 1/4 SEC COR 4 5 71 **Date Set:** 10/31/1990 **County:** Olmsted

Section: 04 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 275' north of E-W pasture fence
This corner is located by GPS measurement

Corner History:

9-1853 Gov't notes, William A. Jones, Deputy Surveyor south between sections 4 and 5. 40.25 chs. set quarter section post 10" diameter burr oak S84°E15° lks. made trench. 50.25 chs. descend a hill and enter brush.

10-31-1990 County Surveyor set up Gov't proportion and line which falls in a cultivated field with no fence in any direction for a quarter mile. Dug 2' x 2' x 15" deep to clay found nothing. Set a telspar pipe with CIC at Gov't prorated position down 16".

12-12-2008 County Surveyor found cast iron cap on telspar pipe down 1.5' in good condition.