Certificate of Location of Government Corner

ID#: 710504 **Description:** 1/4 SEC COR 5 8 71 **Date Set:** 9/19/2012 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 11W **Monument Description:** Brass Plug with Punchmark

Reference Ties:

The monument is at the surface.
The corner falls in centerline of CSAH 10 and 185' north of centerline of field drive west.
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes. William A. Jones, Deputy Surveyor West on true line between sections 5 and 8 40.00 chs. Set quarter section post 7" diameter bur oak N 12º E 368 lks. 6" diameter bur oak S 80º W 432 lks.

6-13-1902 Robert Fraser (Fieldbook 10, page 45) Unrecorded survey could not find corner.

8-22-1990 County Surveyor dug with backhoe in County Road #10, 2' east of centerline and 4' north and 4' south of average of 1/16 fences north and south. There was an old road 2 1/2' deep on clay. Found nothing.

10-30-1990 County Surveyor set 1" square pipe/cap midway and online between section corners.

12-16-2005 County Surveyor found 1" square pipe w/cap in good condition at surface. Measured location using GPS.

9-19-2012 The 1" square pipe was destroyed by CSAH 10 construction. Olmsted County survey crew set brass plug with punchmark at previously measured coordinate position.