Certificate of Location of Government Corner

ID#: 710505 **Description:** SEC COR 5 6 7 8 71 **Date Set:** 11/23/1979 **County:** Olmsted

Section: 05 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of N-S fence and in line with fence west
County Survey Disk in N side CP WNW 1.39'
County Survey Disk in W side gate post SSW 16.01'
County Survey Disk in NE side fence post SE 25.20'
Sign on CP 1 1/2' WNW
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 7 and 8. 80.00 chs. Set post corner to sections 5, 6, 7, & 8 in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage Orange seed NW and SE of trench.

11-1891 Thomas Fraser, County Surveyor (Book A. No. 444), Page 460, and Old Field Book 7, Page 124) "Found remains of stake beside of Post. Mr. John Wiggins said it was where old stake and mound was. He is one of the old settlers and well acquainted with the corner. Set cedar stake notched." He used this corner to set the 1/16th South.

6-1902 Robert Fraser (Old Field Book 10, Page 43), County Surveyor, found red cedar stake.

11-21-1979 County Surveyor found a red cedar stake 28" long and 3" in diameter and tapering to a point standing 1½' East of the corner fence post.

11-23-1979 County Surveyor removed the stake found 11-21-1979 and drove a square pipe with a Cast Iron Cap in the stake hole.

12-20-2005 County Surveyor found telspar w/CIC up 0.8' in good condition. Did not look for any ties.