Certificate of Location of Government Corner

ID#: 710804 **Description:** 1/4 SEC COR 8 17 71 **Date Set:** 9/24/74 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 31' SE of centerline of CSAH 2 on curve
Chiseled cross in NE corner of concrete headwall NW 89.25'
Chiseled square in E corner of concrete headwall W 73.11'
County highway disk in CP SSE 37.52'
Post w/sign 1/2' north
This corner is located by GPS measurement

Corner History:

9-1853 Gov't. Notes William Jones, Deputy Surveyor West on true line between sections 8 and 17. 40.005 Set quarter sections post at average distance in mound of earth and sod. Deposited charcoal, made trench and pits and planted osage orange seed on north and south sides of trench.

11-1891 Thomas Fraser (P. 459 No. 44) found 1' of stake with stones around it midway and on line. Set stone 2 1/2"x5/8"x16".

1963 county highway department (B. 226 P. 15) set C.I.M. over a stone. (Stone was lying flat and was not recorded stone).

9-24-1974 County Surveyor dug with backhoe through fill and found 2 1/2"x5/8"x16" limestone 8.5' deep. Placed a bolt and horse shoe beside the stone. Set C.I.M. with 1/2" rod beneath. Corner lies 1.7' south and 5.6' west of the Co.H.D. C.I.M. Removed Co. H.D. C.I.M.

12-15-2005 County Surveyor found CIM down 1.2' in good condition.

3-6-2007 County Surveyor found CIM down 1.2' in good condition.