Certificate of Location of Government Corner

ID#: 710904 **Description:** 1/4 SEC COR 9 16 71 **Date Set:** 9/2/2008 **County:** Olmsted

Section: 09 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences south and west
County Survey Disk in E side 8" Burr Oak NW 79.1'
County Survey Disk in W side 24" Walnut NE 51.62'
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William Jones, Deputy Surveyor West on true line between section 9 and 16. 40.02 chs. Set a quarter section post at average distance in mound of earth and sod. Deposited charcoal and made trench and pits, and planted orange seeds North and South of trench.

10-1893 William Fraser (P.538 No.499), County Surveyor, found iron stake that a Mr. Smith claimed was in place many years.

10-1900 William Fraser (p.692-8 No.615) could not find iron stake. Ran south line section 9 and set stone and stake 1' deep midway and one line.

9-1-1974 County Surveyor found Fraser's stone 18" deep in a pasture on the NE side of the hillside south of CR 2. Set a C.I.M. over the stone flush with the surface.

5-8-2008 County Surveyor found CIM down 0.2' leaning NW.

9-2-2008 County Surveyor found CIM down 0.2' leaning NW. Removed CIM and found 2" x 9" x 16" stone down 1.9' in good condition. Removed stone and set 5' telspar pipe w/cast iron cap at surface at stone position. Set post w/sign.