Certificate of Location of Government Corner

ID#: 711104 **Description:** 1/4 SEC COR 11 14 71 **Date Set:** 8/28/2002 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' north of centerline of CSAH 2, in line with fence north and 15' east of centerline of field entrance south
Traverse point (Mickow) WNW 53.07'
County Survey Disk in E side CP N 45.67'
County Survey Disk in E side gate post SW 55.52'
County Survey Disk in W side gate post S 50.4'
County Survey Disk in PP #46586 NE 86.69'
Ref pipe SSW 24.06'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes, William Jones, Deputy Surveyor North between sectiond 14 and 15. 40.00 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal, made trench and pits, and planted osage orange seed east and west of Trench.

10-1900 William Fraser (P. 692 No. 615), County Surveyor, found stone and stake by side in line with fence north and south and midway but 11 lks. north of a straight line as Sec. Cor. 10-11-14-15 was reset.

1933 County Highway Dept. (B. 73 P. 3) found limestone with wood stake on south side.

11-1961 County Highway Dept. (B. 252 P. 3) set C.I.M. over limestone found

10-2-74 Roger Brand, County Surveyor dug down beside the C.I.M. set by County Highway Dept. and found stone. Placed a ½"X15" rod on the north side of the stone and a 5/8"X13" rod under the C.I.M.

5-28-92 County Surveyor found C.I.M. down 5" in blacktop in good condition.

5-10-2002 County Surveyor set 1" square pipe w/cap as ref. for 2002 overlay. Tied out corner.

5-29-2002 County Surveyor removed CIM and found rod down 2.2'.

8-28-2002 County Surveyor set 1" square pipe w/cap over p.k. nail at surface.

12-12-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-6-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.