Certificate of Location of Government Corner

ID#: 711304 **Description:** 1/4 SEC COR 13 24 71 **Date Set:** 9/10/1992 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of fence west and 2' east of N-S fence
Spike in 3" Boxelder N 12.14'
Spike in 5" Boxelder E 11.84'
Post w/sign 1' north
This corner is located by GPS reference stations "711304 A & B"

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 13 and 24 40.02½ chs. Set quarter section post at average distance in mound of earth and sod, deposited charcoal made trench and pitts planted osage orange seeds N and S of trench.

5-1900 Robert Fraser, Deputy County Surveyor (Page 679, No. 604) Surveying in section 24 used corner post to fences N-S-E-W claimed to be set where original quarter post stood.

6-12-1992 County Surveyor dug around existing corner post found small pointed post stub or large stake with mark below. Also found 7" diameter post mark at 3' deep running 6" into clay.

9-10-1992 County Surveyor set telspar pipe with cast iron cap at location of 7" diameter post mark found 6-12.

7-21-2009 County Surveyor found CIC on telspar pipe up 0.4' in good condition.