Certificate of Location of Government Corner

ID#: 711506 **Description:** 1/4 SEC COR 15 16 71 **Date Set:** 6/22/2011 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 11W **Monument Description:** Copper plug in concrete road

Reference Ties:

The corner falls 0.1' east of centerline crack of CSAH 10 and in line with fence east.
The monument is at the surface.
This corner is located by GPS reference stations "Delmar and Quincy Twp Hall"

Corner History:

1853 Gov't Notes: Wm. A. Jones, set 1/4 section corner post M&L 40 chs 2640'. 7" Burr Oak N 1 E 547 lks 361'. 9" Burr Oak S 85 W 364 lks 240.2.

11-1900 W.C. Fraser (field Bk.9 P.68-79 S.10) page 77 of field book states at "n" (1/4 15-16) did not locate and could not find any corner.

NOTE: Corner in N-S county blacktop road #10. Farm line east, common land west. Corner near sharp slopes westerly to small high area gentle slope easterly.

8-29-2008 Rod Berg, Olmsted County Survey Department, computed a coordinate position based on measurements to nearby section corners and information found on old highway plans. This position was then used to prepare right of way plats for CSAH 10.

6-22-2011 County survey crew set a copper plug in concrete road using previous coordinates by Rod Berg.