Location of Center of Section

ID#: 711809 **Description:** SEC CEN 18 71 **Date Set:** 7/23/2021 **County:** Olmsted

Section: 18 **Township:** 107N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" square pipe w/cap PLS #18887

County Surveyor recommends using the monumented center of section.

Reference Ties:

The corner falls in centerline of CSAH 7 and 11' north of centerline of field entrance east
The monument is at the surface
County Highway Disc in power pole #33239 W 36.77'
Ref pipe NE 57.80'
This corner is located by GPS measurement

Corner History:

11-21-1892 Thomas Fraser, County Surveyor, (Book A, Pages 500-501, Survey No. 471), set 3"x15"x24" stone at intersecting quarter lines. 1/16th North set 3"x16"x15" stone midway and online at 19.77-1/2 chains (1305.15'). 1/16th East set iron bolt midway and online at 20.01-1/2 chains (1320.99'). 1/16th West set 3"x8"x12" stone online at proportionate government measure 19.95-3/4 chains (1317.20') & 19.81-1/4 chains (1307.63'). 1/16th Center of SE 1/4 set iron bolt midway and online at 20.01-1/2 chains (1320.99') on north-south sixteenth line.

1941 County Highway Department, (CHD Book No. 146, Page 55), found limestone. RPs - Disc in telephone pole NE 28.8', Disc in power pole W 26.5', Disc in fence post E 31.55', Disc in top of fence post SE 71.5'.

9-15-1943 County Highway Department, (CHD Book No. 146, Page 9), 60d spike over limestone. P.I. Sta. 184+82.28. RPs - Spike & Disc in telephone pole NE 59.58', Hub near corner fence post ESE 59.65', Hub NW 73.84'.

2-26-1946 County Highway Department, (CHD Book No. 146, Page 15), 60d spike over limestone. P.I. Sta. 187+57.7.

8-19-1964 County Highway Department, (CHD Book No. 146, Page 15), 3/4" rod. RPs - Spike & Disc in power pole W 36.92', Spike & Disc in corner post E 32.37', Spike & Disc in fence post NE 42.15'.

9-19-1974 Roger Brand, County Surveyor, found 3/4" rod over broken limestone. Set 3/4"x15" rod over broken limestone and set 3/4" rod on east side of limestone.

3-15-1991 Roger Brand & Associates found and used 5/8" rod.

5-9-2002 County Survey Crew found 3/4" rod. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed 3/4" rod.

9-3-2002 County Survey Crew set 1" square pipe w/cap at surface from references for 2002 bituminous overlay project. The corner falls in centerline of CSAH 7 and 11' north of centerline of field entrance east. RP - County Highway Disc in power pole #33239 W 36.77'.

3-6-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

1-15-2008 County Survey Crew found 1" square pipe w/cap at surface in good condition.

10-13-2017 Mark Severtson, County Surveyor, recommends using the monumented center of section based on historical use of this position.

5-21-2021 County Survey Crew found 1" square pipe w/cap at surface in good condition. Removed 1" square pipe w/cap prior to bituminous overlay project.

7-23-2021 County Survey Crew set 1" square pipe w/cap at surface at NAD83 ('96 Adjusted) Olmsted County Coordinates.