Certificate of Location of Government Corner

ID#: 711906 **Description:** W 1/4 SEC COR 19 71 **Date Set:** 6/30/88 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.4'
Traverse point (Green) WNW 151.71'
County Survey Disk in PP NE 8.37'
Post w/sign 1' south
This corner is located by GPS measurement.

Corner History:

10-1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 19 and 24 40.00 chs. Set post for quarter section corner, 10" burr oak N 3" W 131 lks. 10" burr oak S 35° E 53 lks.

11-1875 Thomas Hunter, County Surveyor, Bearing trees gone, dug and found remains of old stake in line of fences running south and east, drove new stake, used this corner to set center of section at intersecting quarter lines.

6-1893 William Fraser, Deputy County Surveyor could not find this corner so located temporary point midway 39.92½ chs. but not on line.

6-23-1988 County Surveyor dug and found old post stub in 8" diameter hole. 6-24-1988 dug some more to cover William Fraser midway point and quarterline west. Also Thomas Hunter's quarter line from east found nothing further.

6-30-1988 County Surveyor set telspar pipe and C.I.C. at post location found 6-23 which would be similar to Thomas Hunter's statement of fences south and east, also near William Fraser's quarter line west.

1-4-2011 County survey crew found cast iron cap on square pipe in good condition.