Certificate of Location of Government Corner

ID#: 712105 **Description:** SEC COR 20 21 28 29 71 **Date Set:** 10/14/2008 **County:** Olmsted

Section: 21 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 5 1/2' north of centerline of E-W twp road and 1' west of fences north and south
This corner is locate by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 28 and 29. 80.00 chs. Set post in mound. Deposited charcoal and made trench pits. Planted osage orange seed NW and SE of trench.

6-1895 W. Fraser (P. 575 No. 526), County Surveyor, found stone in center of road.

10-18-1974 County Surveyor dug with tractor in east-west road and in line with fences. Found a 24" long limestone 10" deep (Broken). Drove a ½" rod on the N. side of bottom of piece of stone and set a CIM overall. Set the top piece of limestone just east of the CIM.

10-14-2008 County Surveyor found CIM without head down 0.3' in good condition. Removed CIM and found bottom half of stone with 1/2" rerod on north side down 1.8' in good condition. Removed stone and set 4' telspar pipe w/cast iron cap down 0.4' at CIM position.