Certificate of Location of Government Corner

ID#: 712204 **Description:** 1/4 SEC COR 22 27 71 **Date Set:** 9/30/1974 **County:** Olmsted

Section: 22 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' south of centerline of CR 107, in line with fence south and 2' east of fence north
Center of 2" shaft CP N 34.1'
County Survey Disk in N side PP NE 109.65'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William Jones, Deputy Surveyor West on true line between sections 22 and 27 39.75 chs. Set a quarter section post from whence Burr Oak 10" N75E l33 lks. Burr Oak 12" S35E 211 lks.

4-1898 William Fraser (P. 625 No. 569), County Surveyor, found old stake remains in the center of the road, midway between rows of trees on North and South sides of the road in line of fences running North and South. Placed stone 4" x 6" x 16" in place of stake found.

5-1900 Robert Fraser (P. 677 No. 602), County Surveyor, found stone set by W. Fraser 2 rods from trees on North and South sides of the road, and in line with fences North and South. Stone lies a little on South side of road.

9-30-1974 County Surveyor dug and found W. Fraser's stone 20" deep with large gear sitting on the top. Stone lies 3' South of the center line of Co. Rd. 107. Placed the gear and the base of a broken C.I.M. on the North side of the stone and drove a 5/8" rod on the South side. Set C.I.M. over all.

10-3-2008 County Surveyor found CIM down 0.9' in good condition.