Certificate of Location of Government Corner

ID#: 712404 **Description:** 1/4 SEC COR 24 25 71 **Date Set:** 7/13/1992 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of CP to fences north and west
County Survey Disk in CP N 2.45'
Sign on CP 2' north
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 24 and 25 40.00 chs. Set quarter section post at average distance in mound of earth and sod deposited charcoal made trench and pits planted osage orange seeds N&S of trench.

10-1896 William Fraser, County Surveyor (Page 595, No. 541) could not find corner so set stake with 6"x12"x20" stone as witness midway and online between section corner 23, 24, 25, 26 and east section corner 24, 25, 39.90 1/2 chains. Also set stone 3"x12"x24" at the sixteenth corner east 19.95 1/4 chains, west set a stake at 19.95 1/4 chains.

6-5-1992 County Surveyor found stone 6"x12"x20" set by William Fraser with square stake mark on the east side of the stone. Also found 1/16th stone east 3"x12"x24" down 12" in old fence row.

7-13-1992 County Surveyor set telspar pipe w/CIC at location of stake mark found.

7-20-2009 County Surveyor found cast iron cap on telspar pipe at surface in good condition.