Certificate of Location of Government Corner

ID#: 712606 **Description:** 1/4 SEC COR 26 27 71 **Date Set:** 1/12/2009 **County:** Olmsted

Section: 26 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 41' north of NW-SE ditch, 1' south of CP for fence north on the north side of ditch
Nail in E side wooden corner post NNE 1.09'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 26 and 27. 40.00 chs. Set a quarter section post in mound. Deposited charcoal, made trench and pits, planted osage orange seed East and West of the trench.

4-1898 William Fraser (P. 625 No. 569), County Surveyor, Found a stake and stone on the West side of the corner post. Left as found.

8-18-1977 County Surveyor found a 4½" x 10" x 12" limestone 2' deep and 1½' SW of the corner post to fences N-S-E. Set a Cast Iron Cap on a square pipe over the stone.

1-6-2009 County Surveyor found telespar pipe w/cap up to 0.3' leaning north. Monument falls 1/2' south of fence end post for fence running north.

1-12-2009 County Surveyor took local ties and removed telespar pipe w/CIC. Found 4 X 10 X12 stone down 2' in good condition and removed. Set 6' telespar pipe w/CIC from ties taken from stone.