Certificate of Location of Government Corner

ID#: 712706 **Description:** 1/4 SEC COR 27 28 71 **Date Set:** 6/22/2011 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.1' east of centerline crack of CSAH 10 and in line with fence west
The monument is at the surface.
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes. William A. Jones, Deputy Surveyor North between sections 27 and 28 40.00 chs. Set quarter section post in mound of earth and sod, made trench and pits planted osage orange seeds east and west of trench.

4-1898 William Fraser, County Surveyor (page 625, 626, No. 567). Could not find anything at this corner or at section corner 21, 22, 27, 28, so set stone at said section corner, prorated measure between east and west quarter corners, prorated from quarter corner north to south section corner 33, 34. Then set temporary stake at quarter corner 27, 28 prorated measure only, not for line.

10-11-1913 County Highway Dept. (Book 1, page 57) No description of corner, appears to be in line of east-west fence.

9-1944 County Highway Department (Book 168, Page 13) Mentions no monument here. Measured from section corner 27, 28, 33, 34 1" X 2" hub. 5289.25' to section corner 21, 22, 27, 28 2" X 2" hub.

6-27-1991 Roger Brand Surveyor, for Tom Ferguson Surveyor set p.k. nail on quarter line from east and online between north and south section corners per County Surveyor's instructions.

5-29-1992 County Surveyor set 1" square pipe w/cap over p.k. nail set by Roger Brand 6/27/91.

3-9-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

6-22-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates.