Certificate of Location of Government Corner

ID#: 712806 **Description:** 1/4 SEC COR 28 29 71 **Date Set:** 5/17/1989 **County:** Olmsted

Section: 28 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls under N-S fence
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 28 and 29 40.00 chs. Set quarter section post in scattering timber Burr Oak 8" N 30º W 145 links Burr Oak 12" S 51º E 278 links

11-7-1988 County Surveyor dug to corner midway and online. Found a loop of wire down under the surface attached going north, found a 9" diameter post mark down 3.0' which matches wire loop found. Hole was 6' x 5' 3.0' deep.

5-17-1989 County Surveyor set telspar pipe with cast iron cap at post mark location found 11-7-1988.

8-22-2008 County Surveyor found telspar w/CIC in good condition up 0.3'. Monument falls just west of N-S fence.