Certificate of Location of Government Corner

ID#: 712904 **Description:** 1/4 SEC COR 29 32 71 **Date Set:** 5/17/1989 **County:** Olmsted

Section: 29 **Township:** 107N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls just west of ditch, 28 1/2' south of fence east and 13' east of N-S fence
County Survey Disk in 11" Burr Oak NW 24.67'
County Survey Disk in 20" Burr Oak NE 32.92'
Post w/sign 2' west
This corner is located by GPS reference stations "Miller & Glenn"

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between section 29 and 32 40.01 1/2 chs. Set a quarter section post Burr Oak 8" N 67º E 236 lks. Burr Oak 10" S 85º E 250 lks. 49.00 chs. Desend a hill and leave timber N and S.

6-1881 John Fraser, County Surveyor (p. 368 No. 359) Could not find quarter section post or witness trees, so he set stone 3" x 8" x 24" midway and online between section corners 40.231/2 chs., set old fence post east of stone. Took new witness trees Burr Oak 3" S 33º 45' E 60 lks., burr oak 4" N 49º 30' E 50 lks.

10-18-1988 County Surveyor set up point using John Fraser bearing and distance from a 20" burr oak. This location was in a road cut bank and near a ditch, dug by hand, found nothing.

5-17-1989 County Surveyor set telspar pipe with cast iron cap at location set up 11-3-1988 from John Fraser witness tree.

3-14-2005 County Surveyor found cast iron cap on telspar pipe at surface in good condition. Set post w/sign 2' west.