Certificate of Location of Government Corner

ID#: 713205 **Description:** S SEC COR 31 32 71 **Date Set:** 11/29/1994 **County:** Olmsted

Section: 32 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.2' north of centerline of CSAH 9 and 93 1/2' west of centerline of CR 132 south
County Survey Disk in PP #52167 SSE 64.06'
County Survey Disk in PP N 63.58'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor West between sections 5 and 32. 80.00 chs. Set post for section corner and drove a charred stake and built mound with trench.

10-1874 Tom Hunter (P. 262 No. 261) County Surveyor, found stone in Road.

8-1887 T. Hunter (P. 419 No. 408) found stone.

1938 County Highway Dept. (B. 94 . 6) found stone. Set ¾" riser.

1943 County Highway Dept. (B. 146 P. 58) found corner.

10-23-1974 County Surveyor dug with tractor and found limestone with ¾" rod riser 7½' deep. Set C.I.M. over ½"X30" rod flush with bituminous surface.

6-10-1993 county highway department took grading ties to C.I.M. before construction of CSAH #9.

12-9-1993 county highway department set 5/8" Iron as Corner in crushed rock surface CSAH #9.

11-29-1994 county highway department set 3/4" Copper rod concrete surface CSAH #9.

3-15-2005 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.

11-9-2006 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.