Certificate of Location of Government Corner

ID#: 713304 **Description:** S 1/4 SEC COR 33 71 **Date Set:** 11/29/94 **County:** Olmsted

Section: 33 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug with punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and 10' west of centerline of field drive south
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 4 and 33. 40.00 chs. Set post and drove charred stake for quarter section corner, built mound with trench, planted osage orange seeds SE, planted apple seeds NE.

10-14-1983 County Surveyor dug 4' deep, found where someone else had dug, probably County Highway Department in 1938 conditions poor on north side of road a little better toward centerline, found nothing.

10-18-1983 County Surveyor dug 4' larger on south side of hole dug 10/14. Found nothing.

5-19-1989 County Surveyor set 1" square pipe with cap on line between section corners and in line of fence north and fence lines in section 4 at the center and 1/16th corner north. Corner falls in centerline of CR #9.

6-1993 county highway department took grading ties to square pipe with cap before construction of CSAH #9.

12-10-1993 county highway department set 3/4" Iron as corner in crushed rock surface CSAH #9.

11-29-1994 county highway department set 5/8" copper plug in concrete surface CSAH #9.

11-7-2005 County Surveyor found copper plug with punchmark in good condition at surface.

3-7-2007 County Surveyor found copper plug with punchmark at surface in good condition.