Certificate of Location of Government Corner

ID#: 713505 **Description:** S SEC COR 34 35 71 **Date Set:** 9/10/98 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.25' south of centerline of CSAH 9, in line with fence north and 77' west of residential driveway north
County Survey Disk in PP SE 66.00'
County Survey Disk in PP WSW 115.64'
Top center TCM box NE 81.5'
Ref pipe N 60.12'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes John Ball, Deputy Surveyor West between sections 2 and 35. 80.00 chs. Set post corner to sections 2, 3, 34, and 35. Burr Oak 10 in. N71½°W 355 lks. Dug trench per instructions.

1941 County Highway Department (B. 125 P. 4) records a stone at the corner. R.P.'s: Disc in Box Elder N.E. 63.25' Hub N.W. 62.45' Hub S. 99.9'.

1970 County Surveyor found the box Elder tree taken as an R.P. in 1941 still standing. Searched for hub set South but couldn't find it.

7-6&7-1977 County Surveyor dug with the backhoe and found a 6"x10"x21" limestone (3½' deep). Set a ½"x25" iron rod on the East side of the stone. Set a C.I.M. over the stone.

7-31-1995 County Surveyor found CIM in good condition. Referenced before construction of CSAH 9

7-15-1998 County Surveyor drilled hole in concrete surface of CSAH 9 at 1995 reference location.

9-10-1998 County Surveyor set 5/8" copper plug w/punch mark at 1995 reference location.

11-7-2005 County Surveyor found 5/8" copper plug w/punch mark in good condition at surface.

3-6-2007 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.