Certificate of Location of Government Corner

ID#: 713604 **Description:** S 1/4 SEC COR 36 71 **Date Set:** 9/10/1998 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 11W **Monument Description:** 5/8" copper plug

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9 and in centerline of twp road south
County Survey Disk in PP NNW 54.00'
County Survey Disk in PP SSW 89.48'
Most NW'ly corner red and white pole shed SE 80.27'
Ref pipe NNE 66.68'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: John Ball Deputy Surveyor. West between section 1 and 36 40.00 chs. Set post and drove charred stake for quarter section corner. Built mound with trench. Planted Osage Orange seeds SE and Apple seed NE.

9-16-1977 County Surveyor dug for corner and found 5" x 7" black mark with wood pieces in clean clay. Mark fell in line of fence North. Set 1" square by 2' long Iron at surface of CSAH 9.

7-18-1995 County Surveyor found Iron in good condition. Referenced corner before construction of CSAH 9.

9-11-1997 County Surveyor set 120d spike in rock surface of CSAH #9 at corner location from reference pipe.

7-15-1998 County Surveyor drilled hole in concrete 0.1' North of centerline crack of CSAH #9 from 1995 reference.

9-10-1998 County Surveyor set copper plug at drill hole location.

12-13-2000 County Surveyor found drill hole w/copper plug deep in hole.

12-12-2006 County Surveyor found drill hole w/copper plug deep in hole.

3-6-2007 County Surveyor found 5/8" copper plug in drill hole.