Certificate of Location of Government Corner

ID#: 720706 **Description:** W 1/4 SEC COR 7 72 **Date Set:** 5/21/97 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of line of fence south and 2' north of line of fence row west
Post w/sign 9 1/2' WSW
This corner is located by GPS reference stations "Rehm I & II"

Corner History:

Gov't Notes Jones 1853 Set 1/4 Section post M & L 40 chains from such. Bur oak 10 in. S30 E 196 lks. Bur Oak 12 in N35 E 250 lks.

5-1886 T. Hunter P 407 No. 396 corner gone, no evidence by digging or there was no knowedge of hwere it originally stood. Set stake M & L 39.91 1/16 east set stake not marked at line and 18.10 then 20.00 to center sec. This done by order of owners as deed requested.

9-1976 County Surveyor dug 3'x3' at intersection of line from W 1/4 Cor. over Center 12 and line from NE 12 to SE 12 Found nothing. Corner in deep fill in E-W fence line.

10-18-1996 County Surveyor dug for T. Hunter Stake set M & L in 1886 and also covering 1/4 line from west which comes 2-1/2' south of M & L position. Found nothing.

5-21-1997 County Surveyor set 4' telspar pipe w/cast iron cap at M&L position. Set sign and post WSW 9-1/2'. The corner falls in bean field down 1.5'. 1' E of fence line south (main line) 2' N of fence row west.

7-6-2011 County survey crew found cast iron cap down 1.6' in good condition.