Certificate of Location of Government Corner

ID#: 720804 **Description:** 1/4 SEC COR 8 17 72 **Date Set:** 9/24/79 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
County Survey Disk on North side of corner post, East 2.23'
The corner falls in E-W fenceline
Sign on CP 2' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 8 and 17. 40.06 chs. Set a quarter section post. Bur Oak 10 in. N55°W 52 lks. Bur Oak 10 in. S60°E 180 lks. 80.12 chs. To section corner.

8-1900 Robert Fraser, Deputy County Surveyor, (Book A, Page 688, No. 611) found old stake about 2' West of corner post of fences, but in line of fences north, south, and east. Witness trees grubbed out and gone. Drove another stake. Used the corner to stake the North 1/2 of the N-S 1/4 line of Section 8.

9-21-1979 County Surveyor dug at the corner post to fences north, south, and east. Found a post stub appx. 1' west and 1/2' south of the corner post and another post stub appx. 1' west and 2' south of the corner post. Found nothing further.

9-24-1979 County Surveyor set a Cast Iron Cap on a square pipe as the corner in line with the main line of the fence south, and west of the corner post. The corner came 2 1/2' west of the corner post location.

10-7-2010 County survey crew found CIC in good condition