Certificate of Location of Government Corner

ID#: 720806 **Description:** 1/4 SEC COR 7 8 72 **Date Set:** 10/16/96 **County:** Olmsted

Section: 08 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3' north of E-W fence and 2 1/2' west of fence south
Post w/sign 2' south
This corner is located by GPS reference stations "Ebling I & II"

Corner History:

Gov't Notes W. A. Jones 1/4 Corner 7-8 40.00 Set a sec. post in mound of earth and sod, deposited charcoal, made trench and pitts, planted Osage Orange E & W of trench.

12-1873 T. Hunter P. 236 No. 238 found original stake in mound. - Meas. south 40.08 (2645.28) to stone -Meas. north 39.92 to stake found in mound some controversy about this mound as it was in cattle corral or near it.

5-1886 T. Hunter P. 407 No. 396 found corner fence post in mound, marked post on west side, tested by meas. from south 40.08 to section corner stone P. 236. - Meas. north 39.92 to stone center road . - 16 West set marked stake M & L 19.88

10-16-1996 County Surveyor dug to cover T. Hunter location of 1/4 corner. Found much wire in digging north of corner post to fence E-W-N. Found piece of fence post in one hole along side an 8" diameter hollow post hole with wood pieces in it and shell pieces of out side post. The bottom of post hole is over 3-1/2' deep in filter area of woods slope from north. This position seems to fit T.H. distance from south hand distance west to 1/4 line in Sec. 7. There were two strands of barb wire one foot deep in ground running E-W past this large post hole & several circles of brace wire & junction wires for C.P. Also found wire running North 1.3' deep below ground. Set CIC/5' long teslpar pipe at 8" post hole location. The corner falls 3' North of E-W Fence & 2-1/2' west of fence south. Placed two stones north & South of CIC @ ground surface. Set sign and post 2' south of mon.