Certificate of Location of Government Corner

ID#: 721105 **Description:** SEC COR 10 11 14 15 72 **Date Set:** 7/12/73 **County:** Olmsted

Section: 11 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' north of fence west
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 14 and 15. 80.00 chs. Set section corner post. Burr Oak 12 in. N26°W 144 lks. Burr Oak 8 in. N15°E 78 lks. Burr Oak 9 in. S40°E 226 lks. Burr Oak 13 in. S 25°W 54 lks.

6-1893 William Fraser (P. 518 Book A), County Surveyor, found old stake in roots of willow tree. Set stone 5"x6"x15" in place of stake.

6-1893 William Fraser (P. 519 Book A), found stone.

1933 county highway department B73 found 4 x 4 x 10 limestone 1/2" iron pipe on north side. All believed to be 1/16 corner in Co. R #2 north. Co. HD B73 P 9 stone mon. in place starting at Hwy 42 as .00. PI stone [triangle] Rt. going E 0° 21' 13+51.6. No on apparently ever saw 10-11-14-15 since set orig.

1962 county highway department 1/2" rod over pointed boulder B226 Disc. power pole NE 34.7' Disc. tele. pole SE 91.25' Sta. 13 +89.38 [triangle] RT 0° 22'

7-12-1973 County Surveyor found recorded limestone under rotted stump. Lowered stone and set C.I.M. over stone with small iron rod on north side and channel type steel post on east side of corner.

11-7-1996 County Surveyor found CIM in good condition with both 1973 steel guard post there in good shape. Set post and sign 1-1/2' East of Mon. The corner falls 1' North of Main line of fence running west and in line of P.P.'s running south.

8-9-2007 County Surveyor found CIM at surface in good condition.