# Certificate of Location of Government Corner

**ID#:** 721209 **Description:** SEC CEN 12 72 **Date Set:** 10/28/1981 **County:** Olmsted

**Section:** 12 **Township:** 107N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #8952

**Reference Ties:**

The corner falls in N-S fence and 10.5' north of fence east.
This corner is located by GPS measurement

**Corner History:**

No Gov't Notes

6-11-1902 Robt. Fraser old fieldbook no.10 P.44 at "1" drove temporary stake and Mr. Richardson said he would put stone. 16 N "3" put stone on line and midway between "B" and 1" short 17-1/2 lks 11.55 or 2628.45 (1314.22) ran both 1/4 lines carefully midway staked E W 1/16 line NW 1/4 section 12. N 1/4 12 sec survey sec 1. 1/16 N of 1/4 11-12 W. Fraser record M&L 1311.75.

10-28-1981 County Surveyor dug from a point 9' north of the traverse nail set on the west side of the corner post to fences N-S-E, north 3' and west 3'. Found a 2"x6"x17" limstone standing and 2' deep 10.3 north of the traverse nail (see drawing for exact). Set 1" sq. by 30" pipe over the stone.

10-29-1981 County Surveyor 1/16 north: dug 3'x3' at a point midway between the stone found at the center 12 and the c.p. at the N 1/4 cor 12 and on line from the S 1/4 cor 12 over the stone found which came 16.19N and 4.28 east of the t.n. (line from S 1/4 came 2.7 west of this point). Did not find anything.

3-17-2010 County survey crew found 1" square pipe without cap up 0.3' in good condition.