# Certificate of Location of Government Corner

**ID#:** 721305 **Description:** SEC COR 13 14 23 24 72 **Date Set:** 2/20/2009 **County:** Olmsted

**Section:** 13 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telespar pipe

**Reference Ties:**

The corner falls 1' west of fence north and 1' west of wooden corner post leaning SE
Post w/sign 0.6' east
This corner is located by GPS reference stations "Walk A & B"

**Corner History:**

Gov't Notes: 80.00 set corner post to sec 13-14-23-24 from whence a Bur Oak 10 in. diameter N 25 E 264 lks. Bur Oak 12 in. in diameter S 62 E 112 lks. Made a trench.

6-1893 W. Fraser P.514 No.481 found old stake from stumps of Se and NE B trees. Set stone 3x24x30 in place of stake. 1/16 east set stake M&L 19.95-3/4 (1317.2) for line south. 1/16 south set stake M&L 19.91 (1314.06) for line east. 1/16 center NW 1/4 x 4 set boulder at inters lines.

6-1893 W. Fraser P.516 No.482 found corner P.514. Meas east to undescribed corner 39.91-1/2 likely P.514. 1/16 north set stake 19.95 M&L.

6-1893 W. Fraser P.519 No.485 found corner P.516. 1/16 west set stone 2x10x16 M&L 19.95. 1/16 north found P.482 stake 19.95 M&L. 1/16 center SE 1/4 14 set stone 2x12x16 inters lines.

8-13-2007 County Surveyor found nothing.

7-14-2008 County Surveyor visited corner area and dug a hole down 3' around corner post and found nothing.

2-20-2009 County Surveyor set 5' telespar pipe w/Cast Iron Cap up 0.3' from computed survey data.