Certificate of Location of Government Corner

ID#: 721405 **Description:** SEC COR 14 15 22 23 72 **Date Set:** 7/7/2011 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The corner falls 3' south of centerline of E-W twp road and 1' east of pole line south
Center of first trans PP S 132.8'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 22 and 23.
80.00 chs. Set section corner post. Made trench. Burr Oak 12 in. N 75°W 347 lks. Burr Oak 10 in. S40°W 413 lks.

9-1893 William Fraser (P.519 No. 485), County Surveyor, found stone claimed to be where orginal corner stood. Corner undesputed. Left as found.

7-12-1973 County Surveyor found recorded limestone 5"x6"x30" down 14" in road. Top piece of stone broke off. Placed on west side of bottom of stone. Placed C.I.M. over bottom piece of stone.

8-9-2007 County survey crew found CIM down 0.6' with head broken off.

7-7-2011 County survey crew removed broken CIM and stone below. Replaced with a 4' telspar pipe with cast iron cap down 0.6'