Certificate of Location of Government Corner

ID#: 721605 **Description:** SEC COR 16 17 20 21 72 **Date Set:** 12/7/89 **County:** Olmsted

Section: 16 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls in centerline of CSAH 2, 4' east of centerline of CR 102 north and in centerline of twp road south
County Survey Disk in W side PP #20657 NW 123.23'
NE Corner main house SW 84.51'
County Survey Disk in NE side westerly of pair of PP SE 146.31'
County highway disk in PP SE 70.28'
County highway disk in PP SW 76.53'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William A. Jones, Deputy Surveyor North between sections 20 and 21. 80.00 chs. Set section corner post-corner to sections 16, 17, 20 & 21. Burr Oak 9 in. N10°W 48 lks. Burr Oak 9 in. N32°E 123 lks. Burr Oak 8 in. S30°E 62 lks. Burr Oak 10 in. 57 1/2°W 81 lks.

7-1870 Robert Perry (P. 130 No. 162), County Surveyor, found a stone and one bearing tree standing.

6-1903 Charles Armstrong (P.130 No. 162), County Surveyor, found a stone P. 130 in the center of the crossroads. Set a stake on the North side.

6-1924 Co. Hwy. Dept. (Bk. 42 P. 10) shows a measure West of 2634.10' to 1/4 Cor. 17-20.

5-1927 Co. Hwy. Dept. (Bk. 37 P. 21) referenced the corner but gave no description of the corner.

5-1933 John Kerr (Bk. 8 P. 77), County Surveyor, dug for the corner but it had been destroyed by grading operations on the road. Set a pump cylinder packed in limestone over a sickle guard as the corner at 2632.5' from 1/4 Cor. 17-20 and in the centerline of the road. The distance also checked from a badly decayed stump Kerr believed to be an original bearing tree.

9-1957 John Kerr (Bk. 70 P.11), County Surveyor, used this corner. Spike in end of pump cylinder.

5-1964 John Kerr (B. 88 P. 20) found the corner in place.

11-10-1976 County Surveyor dug on the South side of a rod found in Co. Rd. #2. Found the rod over a pipe over an old well cylinder packed in limestone (removed all).

11-19-1976 County Surveyor set a C.I.M. over a 1/2"x2' rod as the corner at the location of the well cyclinder.

8-8-1986 County Surveyor set 3/4" pipe w/cap as transit tie, pipe in centerline N-S road opposite 31" Burr Oak and 29' east, angle at 3/4" pipe, angle RT 178° 45' 06" trav PT (markus) to sec cor dis of 195.97 CIM to pipe, pipe to (markus) 1462.54'. RP's to markus CSD in PP #20663 SSW 57.94. NE cor house foundation SW 84.51'. NE cor double garge west 111.21'

1-21-1987 County Surveyor set 1" square pipe w/cap in centerline E-W road centerline of road S and 4' E of centerline road north.

1-28-1987 County Surveyor RP's: CSD in PP with tele box #5400 SW 80.58'. CSD in PP #49781 SE 70.06'. CSD in PP #20657 NW 123.28'.

12-7-1989 county highway department set 5/8" brass plug. CSD in PP #20657 NW 123.23'. CSD in trans pole SE 146.31. Disc in PP SE 70.28'. Disc in PP SW 76.53'.

7-30-2002 County Surveyor found 5/8" brass plug at surface in good condition.

1-3-2007 County Surveyor found 5/8" brass plug at surface in good condition.