Certificate of Location of Government Corner

ID#: 721904 **Description:** 1/4 SEC COR 19 30 72 **Date Set:** 8/22/2002 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls under N-S fence and 1' south of fence row east
Post w/sign 2' East
This corner is located by GPS reference stations "Taco A & B"

Corner History:

1853 Gov't Notes: W.A. Jones. West random 19 & 30. 40.00 set a temp sect post east on true line between sect 19 & 30 course 87° 27' E. 38.76 set a sect post in mound of earth and sod, deposited charcoal. Made trench and pitts, planted Osage Orange seeds N and S of trench.

6-1873 T. Hunter P.227 No.230 found original stake in mound by corner post. 1/16 south set stake M&L 19.88 Due South.

7-1874 T. Hunter P.258 No.258 found stake in mound p.227. 1/16 west set stake on line and 19.63 then 18.42 to sec cor line 71 lks short record 38.76 actual 38.05 38.76 38.05 20.00 19.63 proportions. 1/16 north set temp stake 19.98 M&L for line west. 1/16 south found stake P.227 M&L 19.88. 1/16 corners center SW 1/4 19 and NW 1/4 230 set stakes inters lines.

4-21-1998 Roger Brand & Associates set 5/8" capped pipe #8952 as corner for survey in Sec. 30-107-12.

8-22-2002 County Surveyor removed Roger Brand's 3/4" pipe and dug 3' x 3' x 3' hole to cover T. Hunter's measurements. Found remains of a corner post at Roger Brand's pipe position going down to clay. Accepted Roger Brand's position and set 6' Telspar Pipe w/Cast Iron Cap up 0.2'.

6-27-2011 County survey crew found cast iron cap on telspar pipe in good condition.