Certificate of Location of Government Corner

ID#: 722005 **Description:** SEC COR 19 20 29 30 72 **Date Set:** 7/30/2002 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 102 and 2' south of fence east
Punch hole in W end 18" CMP SW 92.8'
Punch hole in E end 18" CMP SE 94.0'
County Survey Disk in E side PP #20516 NW 79.85'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor North between sections 29 and 30. 80.00 chs. Set section corner post. Made a trench. Burr Oak 8 in. N25°E 410 lks. Burr Oak 12 in. S35°W 461 lks.

6-1873 Thomas Hunter (P. 227 No. 230), County Surveyor, found stake in ground. All bearing trees gone.

5-1886 Thomas Hunter (P. 409 No. 398) found stone in road where old stake stood.

6-1902 Charles Armstrong (P. 58 Book B) used corner.

6-1902 C. Armstrong (P. 60 Book B), County Surveyor, found stone of P. 58 Book B.

5-22-1974 County Surveyor dug with backhoe and found a sandstone boulder. Set a C.I.M. over a 1/2" rod all over the boulder.

7-30-2002 County Surveyor found CIM w/head broken off down 0.5'. Removed CIM found remnants of old fence post and barbed wire fence on East side of monument down 2.0'. Did not locate boulder with probe and did not locate 1/2" iron rod. Replaced CIM from ties taken from center of remaining CIM. Set 4.0' telspar w/CIC down 0.4'.