Certificate of Location of Government Corner

ID#: 722305 **Description:** SEC COR 22 23 26 27 72 **Date Set:** 7/22/2003 **County:** Olmsted

Section: 23 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with waterway east and in PP line
Brass disk in E side PP S 107.45'
Post w/sign 2' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 26 and 27 80.00 chs. Set section corner post. Made trench. Burr Oak 9 in. N 57°E 181 lks.

No other known records of corner.

8-10-1973 County Surveyor found 2"x9"x18" limestone with old post stub by its side over 5' deep under north-south fence. Set a 1 1/4"x42" iron shaft with piece of broken casting on top end, 8" above ground over stone.

10-15-1990 R. Brand & Associates found iron and set yellow fiberglass post near. Took RP: brass disk in E side of Pp S 107.45'.

7-22-2003 County Surveyor found 1 1/4" iron shaft down 0.3' in good condition. Took local ties and removed iron shaft. Set CIC on a 5.0' telspar pipe down 0.1'.

5-9-2008 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.

6-17-2008 County Surveyor found cast iron cap on telspar pipe down 0.5' in good condition.