Certificate of Location of Government Corner

ID#: 722406 **Description:** 1/4 SEC COR 23 24 72 **Date Set:** 5/23/88 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls NE of CP to fences N-S-W
Post w/sign 1' west
This corner is located by GPS reference stations "Walch A & B"

Corner History:

1853 Gov't Notes North between sections 25 and 26. 40.00 chs. Set a quarter section post. Burr Oak 10 in. N71°E 79 lks. Burr Oak 8 in. S20°W 89 lks. 44.50 chs. Stream 5 lks. wide runs S.W.

6-1893 William Fraser (P.514 No. 481), County Surveyor, found stone and proved correct with S.E. bearing tree still standing.

7-18-1973 County Surveyor found 5"x6"x20" limestone just NE of corner post of fences N-S-W. Reset stone over 40d spike with small saw blade on south side and small short rod on north side.

5-23-1988 County Surveyor found stone, saw blade and small rod in good cond. Fence N-S old fence west lying on ground. Set 4' telspar pipe/CIC over nail found under stone, set sign and post 1' west. Set stone at angle on south side of corner with saw blade on east. Small rod on west side of stone.

8-14-2007 County Surveyor found cast iron cap on telspar pipe at surface in good condition.