Certificate of Location of Government Corner

ID#: 722409 **Description:** SEC CEN 24 72 **Date Set:** 7/26/73 **County:** Olmsted

Section: 24 **Township:** 107N **Range:** 12W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1 1/4" pipe

Reference Ties:

The monument is down 0.8'
The corner falls 18' SW of centerline of CR 107 on curve and 8' south of centerline of farm driveway
Center 10" Burr Oak NNW 131.0'
Center 12" Walnut W 102.2'
This corner is located by GPS measurement

Corner History:

6-13-1893 W. Fraser P.514 No.481 found stone as corner. Claimed by Mr. Schmiedebery as set by farmers with "baswood string". Also set stone at 1/16 south. Stone at center proved 18 links too far west and 2 links too far north to be on direct inters lines. Set stake and found a 6" basswood 1 link west. 1/16 west drove stake M&L 19.98 lines N and S. 1/16 south found stone in place to be 11 links too far west and 1 link too far north. Set 2 stones as corner. This corner set true M&L south of center 24 19.96 road shown will east of this 1/16 corner. Plat of survey shows road comes into center 24 from southeasterly almost at corner. 1/16 center SW 1/4 set 2 boulder stones with limestone 2x4x18 on top at inters lines. Found stone here 8 links too far west to be corner.

7-26-1973 County Surveyor dug with tractor. Found recorded basswood stump, must have been about 14" + tree when cut and covered 3' by driveway. Found large top limestone 2x10x18 on east side stump also stake which was displaced in removal of remains of stump. Accepted stone as corner as it came near line of 1/4 corners. Corner comes in old farm drive nearer south edge than to center used to be east outlet to Christopherson farm. 131.0' NNW to center 10" burr oak in level bottom pasture land which stands 15' ± SW'ly from very tall straight 15" dia ± walnut not used as RP as this tree harvest able and could be cut. 102.2 slightly south of due west to center crooked 12" walnut on beginning of up slope west blazed.

5-19-1988 County Surveyor found 1 1/4" pipe in good condition

9-19-1988 McGhie & Betts found and used 1 1/4" pipe.

5-24-1996 Roger Brand & Associates found and used 1" pipe at center of section 24.

5-9-1997 V. Fangman found and used 1 1/4" pipe at center of section 24.

1-6-2011 County survey crew found 1 1/4" pipe in good condition.