Certificate of Location of Government Corner

ID#: 722605 **Description:** SEC COR 26 27 34 35 72 **Date Set:** 6/2/2008 **County:** Olmsted

Section: 26 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' west of N-S fence and 41' south of fence east
County Survey Disk in W side of railroad tie NNE 41.76'
Post w/sign 3 1/2' east
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes William Jones, Deputy Surveyor 80.00 chs. Set section corner post in mound of earth and sod. Deposited charcoal and made trench, pits, and planted osage orange seeds N.W. and S.E. of trench.

No other known records of this corner.

8-16-1973 County Surveyor found a 3 1/2" x7" topped x 15" limestone on line from 1/4 Cor. 26-35 (a stone found) over 1/16 west of 1/4 Cor. 26-35 (a stone found) and double the measure. Set a C.I.M. with top down 15" over a 1/2"x2' iron with original stone on north side.

5-16-1988 County Surveyor found CIM down 12" in fence row. Fence now gone.

6-2-2008 County Surveyor found CIM broken down 0.7'. Found last 2 sections down 1.4' in good condition, took local ties and removed. Found 1/2" rod down 2.4' in good condition, ties matched. Set 5' telspar pipe w/Cast Iron Cap down 1.1' over rod.