Certificate of Location of Government Corner

ID#: 722706 **Description:** 1/4 SEC COR 27 28 72 **Date Set:** 12/23/1986 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' NE of CP
Spike in W side brace post NNW 8.72'
Spike in N side brace post WSW 14.98'
County Survey Disk in SE side 17" Burr Oak SW 26.80'
Sign on CP 1/2' SW
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: W.A. Jones. 40.00 set a section post in which a Bur Oak 12 in. W15E 40 lks (26.4). Bur Oak 14 in. S55W 27 lks (17.82).

5-1872 Silas Hillman (loose leaf letter) Commencing at the NW corner 27. Run south 1/2 mile over runs 49 links. Found old stake and put in stone 12" long.

12-23-1986 County Surveyor found triangular limestone 14" long, 12" wide at the base and coming to a point, top down 8". Also found 12" x 2-1/2" by 4" x 1-1/2" thick limestone lying on its side. Set telspar/CIC where triangular limestone set, set triangle limestone on N side and other stone on south. CIC .6 NE of NE edge of new treated c. post with sign. RP's: Spike in brace post W side NNW 8.72'. Spike in brace post N side WSW 14.98'. Spike and CSD in SE side 17" Burr Oak S47°W 26.80'.

5-29-2008 County Surveyor found cast iron cap on telspar pipe up 0.2' in good condition.