Certificate of Location of Government Corner

ID#: 723405 **Description:** S SEC COR 33 34 72 **Date Set:** 6/30/2005 **County:** Olmsted

Section: 34 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 4' south of centerline of CSAH 9 and 1 1/2' west of fence north
County Survey Disk in E side PP SW 57.05'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor
West between sections 3 and 34. 80.00 chs. Set post and drove charred stake. Built mound with trench. Planted plumb SE and apple seed NE.

1953 County Highway Department assumed corner.

7-17-1973 County Surveyor used dozer to explore. Found old cedar stake as those found at most corners on this range line. Found and removed county assumed corner. Drove wood hub in its place. Corner found 4.3' south and 1.3' west of county assumed corner.

11-20-1974 County Surveyor set 1 1/4" pipe as final corner. Corner falls 4.3' south and 1.3' west of County Highway Department P.I. rod.

6-12-2001 County Surveyor found 1 1/4" pipe at surface in good condition.

7-15-2003 County Surveyor found 1 1/4" pipe at surface in good condition.

6-30-2005 County Surveyor set copper plug with punch mark at surface from coordinates. Monument falls 4.23' south of centerline crack of CR 9 and 1 1/2' west of fence running north. CSD in east side of PP no # SW 57.05'. All other ties gone.

4-27-2009 County Surveyor found 5/8" copper plug w/punch mark at surface in good condition.