Certificate of Location of Government Corner

ID#: 723505 **Description:** S SEC COR 34 35 72 **Date Set:** 11/29/94 **County:** Olmsted

Section: 35 **Township:** 107N **Range:** 12W **Monument Description:** 5/8" copper plug w/punch mark

Reference Ties:

The corner falls 0.1' north of centerline of CSAH 9, in line with fence north and 1' west of fence south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor West between sections 2 and 35. 80.00 chs. Set post and drove charred stake for corner to sections 2, 3, 34 & 35. Built mound with trench per instructions. Planted S.E. plumb, N.W. apple seed.

6-1874 Thomas Hunter (P.247 No. 248) County Surveyor, found a stone in the center of the road as the section corner.

7-14-1976 County Surveyor dug with the backhoe and found a 4"x6"x20" limestone 4 1/2' deep. Set lawnmower blades on the North and South sides of the stone.

7-16-1976 County Surveyor set a C.I.M. over a 1"x24" pipe over the stone as the corner.

5-21-1993 County Surveyor took grading ties before construction of CSAH 9.

12-9-1993 County Highway Department set 5/8" rerod @ corner location in crushed rock CSAH 9.

11-29-1994 County Highway Department set 5/8" copper rod in concrete CSAH 9 as final corner.

12-12-2006 County Surveyor found 5/8" copper plug at surface in good condition.

3-6-2007 County Surveyor found 5/8" copper plug at surface in good condition.