Certificate of Location of Government Corner

ID#: 723606 **Description:** 1/4 SEC COR 35 36 72 **Date Set:** 6/23/1988 **County:** Olmsted

Section: 36 **Township:** 107N **Range:** 12W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface.
The corner falls on east side of CP to fences E-W-S
County Survey Disk in 15" Burr Oak NW 36.73'
County Survey Disk in Burr Oak ENE 43.92'
Sign on CP 1' west
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes W.A. Jones 40.00 set a section post Burr Oak 6 in N 62° E88 lks. Burr Oak 6 in. S.07° W85 lks = 56.1'.

6-1893 W. Fraser P. 517 No. 483 found stone, tested by SWBT and stump of NEBT. They agreed within one link. used and left as found 1/16 east set 2 stones 2 x 9 x 15 and 2 x 9 x 12 M & L 19.97-1/2.

6-19-1978 Yaggy Associates found and used stone.

W.H.K.S. both found and used stone.

6-20-1988 County Surveyor found 5" x 5" x 20" limestone on E. side of C.P. fences E-W-S, Dug out stone, Fd dark mark in clay beneath stone

6-23-1988 County Surveyor set 4 telspar pipe/C.I.C. with stone dug down 1' north, put sign on corner post. R.P.s spike & C.S.D. in Burr Oak ENE 43.92.

6-23-1988 County Surveyor at 1/16th east dug 4' north & 5' east of trav. nail set 6-21-1988, to cover line & full w.f. meas from west fd nothing, many small pieces of limestone in the digging

1-6-2011 County survey crew found cast iron cap on sq. pipe in good condition