Certificate of Location of Government Corner

ID#: 730104 **Description:** 1/4 SEC COR 1 12 73 **Date Set:** 12/15/2004 **County:** Olmsted

Section: 01 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 5' south of centerline of CR 124 and 7' west of fence north
County Survey Disk in NE side PP #20073 SE 58.58'
County Survey Disk in W side 16" Cedar SSW 60.43'
Punch mark in W end 18" CMP S 41.12'
Punch mark in E end 18" CMP S SE 48.81'
Ref pipe SE 68.71'
This corner is located by GPS measurement

Corner History:

Gov't Notes 40.00 set temp. section post west on true line between 1 & 12 9° 13' East. 39.96 Set section post. 6" Burr Oak N37 E131 links, 6" Burr Oak S80 E58 links.

5-1872 T. Hunter P. 202 No. 211 found stub, SE bearing tree gone, NE bearing tree stump proved stake correct. Set marked stake as 1/4 corner. 16W set stake M&L 19.84 S 891/2 E (1309.44). Measure north 39.85 N 20' E. (2630.1).
Measure east 39.78 (2625.5). Tom Fraser BK#7, Pg. 20 shows stone as corner (2"x6"x24").

8-25-1976 County Surveyor found stake - set 1/2"x25" rod. Corner 5' south of centerline.

11-2-1992 Roger Brand & Assoc. set 3/4" Square head drag tooth from ties.

7-3-2003 County Surveyor found dragtooth at surface. Took local ties and removed. Found 3/4" pipe down 1.4' and removed. Will set 1" square pipe back at dragtooth location.

7-14-2003 County Surveyor set 1" square pipe w/cap at surface from local ties.

5-17-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-18-2004 County Surveyor set reference pipe for 2004 overlay.

8-3-2004 County Surveyor removed 1" square pipe w/cap for 2004 overlay.

12-3-2004 County Surveyor set p.k. nail at surface from 2004 overlay tie-out.

12-15-2004 County Surveyor set 1" square pipe w/cap at surface over p.k. nail. Monument falls 7' west of fence north and 5' south of centerline of CR 124. CSD in pp #20073 SE 58.58'. Did not check any other ties.

9-20-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.