Certificate of Location of Government Corner

ID#: 730309 **Description:** SEC CEN 3 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 03 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and in centerline of field drive east
The monument is down 0.8'
Reference pipe E 87.24'
This corner is located by GPS measurement

Corner History:

5-13-1873 T. Hunter P.223, No.226 set stake at inter lines. 3 Bearing trees taken (all gone). 16 so set stake M&L 19.92 (1314.72). 16N set stake on line & north 19.99 then 20.86 (1376.76 to N1/4 3).

11-25-1964 J. Kerr set rod in blacktop at true inter lines, no ref's. Measure east 2629.47 set point M&L. Measure north 2694.84 or 1318.61 then 1376.23. Set corner at this point & 33' east or 50' east center NE1/4 S3. Set prop corner N-S 1/16 line 1374.98 and 1318.92. Angle at center 3 N&E 90° 39'.

6-8-1994 County Surveyor found 5/8" iron. Set reference pipe w/cap east in fence row. Referenced before cold recycling bituminous project, removed Iron.

9-24-1994 GGG used corner for survey in SE 1/4.

11-14-1994 county highway department set 1" square pipe w/cap at surface from 1994 overlay tie out.

10-17-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

1-9-2009 McGhie & Betts found and used 1" square pipe w/cap at center of section 3.

5-23-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.