Certificate of Location of Government Corner

ID#: 730605 **Description:** W SEC COR 6 7 73 **Date Set:** 10/1/2012 **County:** Olmsted

Section: 06 **Township:** 107N **Range:** 13W **Monument Description:** Telspar Pipe with Cast Iron Cap

Reference Ties:

The monument is up 0.4'
The corner falls in line with N-S fence.
Post w/sign 2' North
This corner is located by GPS reference stations "Cow Woods A & B"

Corner History:

Gov't Notes: 80.00 Set post corner to section 1-6-7-12 Burr Oak 10 N 0º W 212 Burr Oak 14 S 10º W 450 links Burr Oak 10 N 60º E 66 links

12-26-1899 R. Fraser (Book A, P. 645 No. 581) S12 Geo Vikon Found stake with broken stones by its side, set new stake.

1-3-1900 R. Fraser (Book A, P. 646 No. 582) S 1-2-11-12 Found stake and broken stones P. 645.

3-13-1902 W. Fraser (Book B, P. 32B) S12 Baker, Greenwood Found corner as described P. 645 & 646. 1/16 west set temp stake M&L 19.97'. 1/16 center NE1/4 12 set stake M&L 19.87' on N-S 1/16 line. Corner now 2" iron shaft in concrete pillar used by state and other surveyors.

3-28-1990 County Surveyor shot 2" iron shaft up 4' as corner. RPs- NW corner utility shed e 12.8', SW corner utility shed SE 17.4', and wire fence north for ± 50' & a stub fence east ±50'. Surveyor - measured to a 2" iron shaft up 4' as the corner.

12-22-1997 McGhie & Betts found 2" axle shaft in concrete 4' above ground and took new references.

11-22-2002 County Surveyor found axle shaft up 4.0'. Set sign & post 1.0' West of corner. Monument falls in backyard of house #1901 (no # on house).

10-1-2012 Olmsted County survey crew found axel shaft in good condition. Removed axel shaft and replaced it with a 3.5' telspar pipe with cast iron cap.