Certificate of Location of Government Corner

ID#: 730704 **Description:** 1/4 SEC COR 7 18 73 **Date Set:** 12/11/2003 **County:** Olmsted

Section: 07 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

E'ly edge basement window 2nd from W end of house NW 54.58'
SE corner of house NW 31.37'
SE corner of chimey NW 36.97'
NE corner of house NNW 81.42'
Post w/sign 2' WNW
This corner is located by GPS reference stations "Curtis A & B"

Corner History:

Gov't Notes Set temp section post east between section 7&18. S89° 40'E. 38.72 set section post. 12" Burr Oak N78 E250 links, 14" Burr Oak S80 E370 links.

2-1858 T. Hunter page 49 No.72 show 1/4 post set 1/16th corners east and west.

4-1864 P.C. Compton Page.80 No.120 shows 1/4 corner 1/16th east set with Brg tree (14" Burr Oak S72°W 52 lks.

8-1871 T. Hunter P.187, No.198, corner gone, reset stake. 16S set stake.

10-18-1877 T. Hunter P.322, No.316, corner culvert out. Reset from Bearing tree, 1/4 west set stake. Set 1/64 corner. 16 N set stake M&L.

11-12-1888 T. Hunter found corner, 1/16 stake south took bearing tree to 1/4 7-18-4" Burr Oak S 5°e 20 links. 6" Burr Oak south on line 213 links.

7-31-1980 County Surveyor, (1/4 corner 7-18) Found 11/4" pipe with steel fence post beside.

12-20-1989 WHKS, found 1 1/4" pipe, set sign & post ± 1.0'N.

5-6-1974 County Surveyor dug around here 14' west of pipe for T. Hunter corner (found nothing).

6-27-2003 County Surveyor found 1 1/4" pipe in good condition.

12-11-2003 County Surveyor found 1 1/4" iron pipe up 0.5'. Removed pipe and set 6' telspar pipe w/CIC up 0.1' from local ties.