Certificate of Location of Government Corner

ID#: 731204 **Description:** 1/4 SEC COR 12 13 73 **Date Set:** 9/1/1976 **County:** Olmsted

Section: 12 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' south of E-W fence, 31' west of gully and 27' east of fence north (around gully)
County Survey Disk in W side 22" Jack Oak NNE 9.19'
County Survey Disk in W side 9" Burr Oak S 35.50'
County Survey Disk in N side 6" Burr Oak ESE 52.57'
Post w/sign 2' south
This corner is located by GPS reference stations "Sleeper Cab B & C"

Corner History:

1853 Gov't Notes - Yerby, 40.00 set temp sec post west on true line between 12&13, 9° 16' E. 39.91/2 set section post. RPs- 12" burr oak W55 E 95 links, 10" burr oak S7°E 120 links.

?? Tom Fraser, Bk#7, Pg.20 - Shows stone as 1/4 corner. Bearing Tree - N87°W 3 links 12" Burr Oak. 1/16 corner shows 6"x16"x24" stone.

1889 Thomas Fraser (Old Field Book #7 P. 20), County Surveyor, records a 1 1/2" x 5" x 14" stone at the corner and stones at the 1/16th North, the center of section 12, and at the North 1/4 Cor. Sec. 12.

8-11-1976 County Surveyor found pieces of limestone beside corner post.

9-1-1976 County Surveyor set CIM over 5/8" x 18" rod as the corner on line from the North 1/4 Cor. Sec. 12 over the center of section 12 (found) and at double the distance from the center of section 12 over the 1/16th South (found).

9-20-2006 County Surveyor found CIM down 0.3' in good condition. All ties there but did not check. Fences are all there and in good shape. Set sign and post 2.0' south.