Certificate of Location of Government Corner

ID#: 731305 **Description:** SEC COR 13 14 23 24 73 **Date Set:** 12/7/1989 **County:** Olmsted

Section: 13 **Township:** 107N **Range:** 13W **Monument Description:** 5/8" brass plug with punch mark

Reference Ties:

The monument is at the surface
The corner falls in centerline of CSAH 2
County highway disk in Ash NW 96.10'
County highway disk in PP SSW 146.00'
County highway disk in PP NW 65.50'
Ref pipe N 228.37'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 80.00 set section corner post, made trench. RPs- 12" burr oak S15°E448 links.

7-1874 T. Hunter P.258, No.258 - Set no permanent corner measure east 39.65 (2616.9 to corner) set from witness tree stump (See T. Hunter Bk5 P.117 Sec. 13).

1937 county highway department B.92 P.77 Found sq limestone (stone placed where old stake was found by H. Behnken years ago). Set iton sash weight over limestone & CIM over all.

11-15-1973 County Surveyor found limestone 3.6' deep and C H.D. hubs. Set a C.I.M. flush with road surface and set a sash weight under monument over stone.

8-7-1986 County Surveyor set transit ties 3/4" pipe/plastic cap opposite pp#19550 on west side N-S twp road centerline.

12-7-1989 county highway department set 5/8" brass plug in centerline CR 2.

10-8-1996 County Surveyor found brass plug with punchmark at surface in good condition.

9-20-2006 County Surveyor found brass plug with punchmark at surface in good condition.

8-4-2011 County survey crew found brass plug with punchmark in good condition.