Certificate of Location of Government Corner

ID#: 731405 **Description:** SEC COR 14 15 22 23 73 **Date Set:** 12/7/1989 **County:** Olmsted

Section: 14 **Township:** 107N **Range:** 13W **Monument Description:** 5/8" Brass Plug w/punch mark

Reference Ties:

The corner falls in centerline of CSAH 2 and 3' west of fence north
County Survey Disk in small Maple NNW 69.86'
County highway disk in SW side Maple NW 90.71'
County highway disk in PP SW 72.73'
County highway disk in CP N 52.61'
This corner is located by GPS measurement

Corner History:

1853 Yerby, Gov. Notes, 80.00 set section corner post, made trench. 9" Burr Oak N13 E267 links.

5-1875 T. Hunter P.273, No.271 - Corner gone. Set temp point for measure south. South set 1/16 temp point by measure 19.95'.

1949 McGhie - 3/4"x12" iron rod.

8-5-1986 County Surveyor found 1/2" iron and referenced before road construction. Drove 3/4" pipe with plastic cap as reference.

12-7-1989 County Highway Department set 5/8" brass plug in centerline CR #2.

10-8-1996 County Surveyor found 5/8" Brass Plug w/punch mark at surface in good condition.

10-19-2005 County Surveyor found 5/8" Brass Plug w/punch mark at surface in good condition.