Certificate of Location of Government Corner

ID#: 731504 **Description:** 1/4 SEC COR 15 22 73 **Date Set:** 7/28/1989 **County:** Olmsted

Section: 15 **Township:** 107N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and 7' north of centerline of Haverhill Town Hall driveway east
NE cor main part of townhall ESE 120.7'
County Survey Disk in PP #26403 WSW 30.71'
County highway disk in post W 49.21'
Ref iron N 250.90'
Ref pipe E 70.59'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby, 40.00 set temp sec post west on true line course 8° 58'E. 40.00 set section post. 12" Burr Oak N18 E 28 links. 13" Burr Oak S44 E26 links.

5-1875 Hunter, P.273, No.271, found stone, Bearing trees gone. 16D set stake M&L 19.921/2 for line east.

1923 County Highway Department Bk#31 P. 28 - shows they used a corner.

8-1-1966 J. Kerr set CIM over pipe now in place as corner.

3-12-1974 County Highway Department (Book 376, Page 15) found CIM and took ties. Used monument for CSAH 2 alignment PI Station 305+26.3

9-4-1985 County Surveyor found CIM OK.

8-6-1986 County Surveyor removed CIM head broken but still in place.

7-28-1989 County Surveyor set 1" square pipe/cap on CR #11.

6-1994 County Surveyor found 1" square pipe/cap. Set ref point 1" square pipe/cap in line w/top cen light South side of radio tower east.

10-19-2005 County survey crew found 1" square pipe w/eroded cap down 0.2' in good condition. Replaced cap.

5-23-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.