Certificate of Location of Government Corner

ID#: 732709 **Description:** SEC CEN 27 73 **Date Set:** 11/14/1994 **County:** Olmsted

Section: 27 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11 and in line with fence west
The monument is down 1'
County highway disk in PP E 49.98'
1/2" rod W 100.0'
Ref pipe W 68.87'
This corner is located by GPS measurement

Corner History:

5-17-1876 T. Hunter, P.293 No.288 found stake, 16 east set stake M&L 19.901/2 (1313.73).

1963 J. Kerr set CIM over rod.

8-13-1965 J. Kerr reset CIM after grading.

8-12-1968 J. Kerr drove 3/4"x12" rod.

12-14-1984 Yaggy Associates found and used CIM.

2-17-1987 WHKS found and used iron rod at center of section 27.

7-1989 County Surveyor found 3/4" rod in CR.11

9-11-1989 V. Fangman found and used 3/4" rerod.

9-8-1992 Roger Brand & Associates found and used 3/4" iron at center of section 27.

6-1994 County Surveyor found 5/8" rerod. Set ref pt 1" square pipe w/cap, before cold recycling bituminous surface of C.R. #11

11-14-1994 County Highway Department set 1" square pipe w/cap at surface from 1994 overlay tie out.

12-1-2003 R. Brand & Associates found and used 1" square pipe w/cap.

10-18-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.

5-20-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.