Certificate of Location of Government Corner

ID#: 733009 **Description:** SEC CEN 30 73 **Date Set:** 4/29/1987 **County:** Olmsted

Section: 30 **Township:** 107N **Range:** 13W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of CP to fence N-S-W
R/W post and sign 2' west
Post w/sign 1' north
This corner is located by GPS measurement

Corner History:

9-25-1891 T. Fraser, P.456 No.440 set stake, 16 south set stake.

12-3-1900 W. Fraser P.700, No.616 Weber found stake.

4-15-1977 McGhie & Betts set 5/8" pipe w/cap at intersecting quarter lines.

11-27-1978 McGhie & Betts found and used 5/8" pipe.

8-9-1983 Yaggy Associates found and used 5/8" pipe.

4-29-1987 County Surveyor set cast iron cap on telspar pipe as corner according to CSAH 22 R/W plat #46. Corner .08' West & .15'N of McGhie & Betts pipe/cap. Set R/W marker, sign & post 1' north. Corner 2' south of fence corner to fence N-S-W.

5-10-2002 Pape Engineering & LS found and used monument at center of section 30.

12-19-2003 County Surveyor found cast iron cap on telspar pipe at surface in good condition. R/W post and sign 2.0' West.

10-29-2004 Yaggy Colby found and used Cast Iron Cap on telspar pipe.