Certificate of Location of Government Corner

ID#: 740204 **Description:** 1/4 SEC COR 2 11 74 **Date Set:** 8/17/63 **County:** Olmsted

Section: 02 **Township:** 107N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1/2' NE of CP for fences West & South
Spike in hub in 18" Maple tree NNE 45.3
Spike in hub in 10" Burr Oak tree S 72.8'
Post w/sign 2' East
This corner is located by GPS refrence stations "Horse Pasture A & B"

Corner History:

Gov't Notes - M. Kerrick 1854 40.00 Set temporary 1/4 steel post. West on true line between section 2-11 variation 8º 15'. 40.00 Set 1/4 sectio post. White Oak 10" S13W 30 lks. Jack Oak 10" N25W 60 lks.

3-1856 T. Hunter shows 1/4 post, 1/16 west 20.02 chs. M&L Bearing Tree to 1/16 cor. N 701/4ºE 147 lks., 1/16 North 20.34 chs. M&L

1-1874 Thomas Hunter (See field book 3 p. 67-70) P. 237 No. 239 found stake, badly rotted but standing. Witness trees are erronous having been cut and sprayed where markings were as Surveyor had returned to correct mistake of some kind detailed explanation, small lots survey near SW corner Sec. 2.

6-1900 Robert Fraser P. 646 - 6652 No. 582 found no stake, but found erronous witness trees. Hunter claims stake was 2 rods and south of witness trees location. After setting corner stake M&L either 39.943/8 or twice. 19.943/8 Farmer said he would set stone. 16 East drove Burr Oak stake M&L 19.943/8 (1316.3±)

6-1900 R. Fraser - Field Bk. 15 p. 3-20 At "B" - 1/4 Cor. 2-11 set stake marked 1/4 S and Mr. Blanchard said he would put in stone. Took witness trees N78ºE 19 lks. Jack Oak 6" S11ºE 17 lks. Jack Oak 5" N58ºW 151/2 lks. Basswood 8" at 1/16 cor-west set stake marked and took witness trees. 531/2E 191/2 lks. Jack Oak 6" - N301/2 W 17 lks. Jack Oak 4" R.F. 1900 survey con't at cor. SW 1/2 Sec. 2 set stake marked and stone. Took witness trees S13ºW lks. = 20.46', Pin 0.12" & N881/2ºW red elm 8" 16 lks. = 10.56'.

4-1913 D. Williams P. 200 B 1/16 west iron stake. 1/16 north found stake & bearing tree, limestone with ±. Center SW 1/2 2 set.

1954 J. Kerr B, 59 Pg. 1&5, Run line SW cor. 2 to S1/4 2 2631.87 found stone with iron bolt by side. Set property corners and lines between near rod.

8-17-63 J. Kerr set C.I.M. in place of corner stone on hard rock base. Corner line just east of N-S wood fences on hilltop above Ted Mitchell building site. Nail & hub 18" Maple NNE 45.3 Nail & hub 10" Burr Oak S 72.8

1964 J. Kerr B. 88 P. 40 ran line from S 1/42 east to 1/16 stone (rough) R1316.3 total 1315.5 set property corner for line north at various points see book.

6-11-1980 County Surveyor (1980 Remonument Book) 1/16 North: Found 1 1/4" pipe up 1' east of the base of old corner post to fences. N-S-W there was a 2"x9" topped shattered limestone sticking 4" out of the ground .5 south and .35 west of the pipe. (See 1913 D. Williams)

5-27-2003 County Surveyor found CIM at surface in good condition.